



Personal Protective Equipment Technical Bulletin

MANUFACTURER

Raven Lining Systems
13105 E. 61st Street, Suite A
Broken Arrow, OK 74012
(918) 615-0020

DESCRIPTION

The following is a list of recommended PPE, which should be utilized to reduce the exposure of personnel to hazards while performing functions related to the installation of Raven Lining Systems products.

This list is provided for informational purposes only. Employers should consult with safety professionals when selecting safety supplies and equipment to ensure proper application and compliance with federal, state and/or other requirements. Employees are required by law to receive proper equipment and training in the use of such equipment to prevent exposure to hazards in the workplace.

Eye protection such as safety glasses, face shield, full-face respirator, blast hood/helmet, etc. to protect eyes from debris, blast media, shavings, coating overspray and other matter, which may cause injury or irritation of the eyes.

Respiratory protection such as dust masks, half-face or full-face air purifying respirators, supplied air respirators, or SCBAs; to protect the respiratory system from airborne particles, harmful fumes, oxygen deficiency, toxins or other matter, which may cause acute or chronic respiratory problems.

Protective clothing such as gloves, rubber boots, rain suits, tyvek suit, or chemical suit to protect personnel from contact with harmful materials.

Protective/waterproof footwear with steel toes to prevent injury from impingement and contact with harmful materials.

Hardhat to protect personnel from falling objects and contact with low overhead or sharp objects.

Protective shielding for extremities for use with high or ultra-high pressure water cleaning.

Special Considerations

Air purifying respirators DO NOT protect the user from toxins, such as Hydrogen Sulfide, and oxygen deficiency. APR cartridges should be selected based upon the type of exposure expected and stored/replaced according to the manufacturer's recommendations.

Exposure to certain chemical and solvents may require specialized PPE. Consult SDS and safety equipment suppliers for information. Basic PPE such as gloves, safety glasses, hard hats and steel toe boots should be worn at all times when any hazards exist.

Additional safety equipment is required for Confined Space Entry and fall protection, consult a safety professional.