





Membranes

BRANDS YOU KNOW. PERFORMANCE YOU TRUST.

CURRENT ISSUE | PRODUCTS | STOREFRONTS | TOP PROJECTS | WEBINARS | EVENTS | WHITE PAPERS | TECH REVIEWS

Industrial

Pumps

Pipes

f 🛢 🖇 in

Meters

Smoothing the Surface

Fri. 2015-04-10 12:41

Archives



Buyer's Guide

Escondido, Calif., facility uses epoxy product for extensive infrastructure

The Escondido-Vista Water Treatment Plant in Escondido, Calif., supplies vater to over 25,000 residential, commercial and agricultural customers. As the city has steadily grown, the water treatment plant's aging infrastructure has

Upon inspection of the facility, it was concluded that the plant's 90,000 sq ft of concrete showed signs of degradation with exposed aggregate. Officials decided to rehabilitate the current facility rather than build a new one in order to save taxpayers' money.

National Coating and Lining Company (NCLC), a Raven certified applicator, won the project. Based in Murrieta, Calif., NCLC offers 40 years of combined expertise in the restoration and protection of concrete and ferrous metals throughout the water and wastewater industry, so it was an exceptional fit for the type of project envisioned for Escandida

The biggest challenge associated with the project was accommodating the city's needs while completing a 150-day project in 60 days. The overall goal was to limit the time the plant was affected in order to continue to provide an adequate water supply to the city with the summer approaching.

In addition, the process of applying coating was restricted to times when temperatures were relatively lowduring late-night shifts to aid in diminishing moisture vapor transmission. Also, coating concrete with an excessively rough surface profile without a cementitious resurfacing proved difficult, and workers had to contend with minor infiltration

"NCLC opted to increase the film thickening from the specified 80 mm to 160 mm in lieu of concrete restoration in order to expedite the completion date," said Tom Unsell, NCLC vice president. "To accommodate for the accelerated turnaround, we increased manpower and equipment, as well as working nights."

The surface of the structure was degrading due to the chemicals used in water treatment. After the City of Escondido assessed the facility, it was determined that a 100% epoxy product-which must be NSF/ANSI 61-certified-would protect and reinforce the structure from further deterioration. The technology to be used by NCLC would be a fluidapplied plural component 100% solids enoxy, in lieu of a cementitious underlayment with an enoxy topcoat. Using Poxy as the resurfacer and epoxy topcoat would allow faster turnaround while providing a superior coating system

Eliminating cementitious repair saved time and money—workers did not have to wait for the concrete to cure, and a secondary surface preparation of the cementitious repair was eliminated. By utilizing the coating over a rough substrate, adhesion to the structure was increased and structural integrity was reinforced.

In addition, two times the millage increased thickness of the polymer and allowed for improved resistance to hydrostatic loading and additional abrasion resistance. It also increased the service life of the structure

Process

The basins were drained, and all remaining solids and debris were physically removed. A combination of a 5,000-psi hydro-blast and abrasive blasting was performed over entire structure, with the goal to achieve a minimum concrete surface profile of CSP-3. At the edge of where the coating application ceased, termination grooves and keyways were utilized to assure that superior adhesion existed. After completing surface preparation, a final low-pressure water rinse was conducted to wash away the loose dust and debris. After the substrate had dried, two coats of primer were applied to reduce moisture vapor transmission. The first coat of AquataPoxy A6 Thick was applied with a back trowel to smooth the surface of the coating, and once that coat was tack-free, a second coat was applied. Any pinholes found after holiday testing were repaired within the recoat window; pinholes discovered after the recoat window had expired were prepared and then repaired according to Raven recommended procedures.

The solution implementation benefits the City of Escondido by providing an increased service life of the structure, as well as protecting the life of the investment. The cost of the project was \$1.2 million

Roxanne Cook is the director of marketing for Raven Lining Systems. Cook can be reached at cookr@ravenlining.com.

Company Information



Raven Lining Systems 13105 East 61st St.

Broken Arrow

800.324.2810

http://www.ravenlining.com











More like this

- Corrosion Resistance
- Protecting Concrete Tanks in Water and Wastewater Treatment Plants · Pulling the Plug on Corrosion
- · High Performance Coatings Meet Stringent Standards At Iowa City Water Treatment Facility . Maintenance History of Four Steel Water Tanks

Energy Small Systems

> sian Pro for FREE GENERAC INDUSTRIAL

VISIT OUR STOREFRONT

Raven Lining Systems

RELATED ARTICLES

Data Retrieval Delivery Made Easy Early 2014 reports revealed that mobile device Internet usage exceeded PC/desktop usage for the first time in history. While on the consumer...

The Need for Conservation

In my December 2014 column, I wrote about water conservation-or, more appropriately, vater conservation gone awry. This is pretty familiar territory...

Solving a National Crisis

In its 2013 Report Card for America's Infrastructure, the American Society of Civil Engineers gave U.S. water infrastructure a barely passing ".

MORE ARTICLES +

SMART H2O SUMMIT 2015

EXHIBIT TODAY AND REACH THE KEY DECISION MAKERS

CLICK HERE FOR MORE INFORMATION! >